

RECEIVED

APR 11 1980

STATE OF IDAHO DEPARTMENT OF WATER RESOURCES WELL DRILLER'S REPORT

RECEIVED DEPARTMENT OF WATER RESOURCES

State law requires that this report be filed with the Director, Department of Water Resources within 30 days after the completion or abandonment of the well.

ACT 31 1979

1. WELL OWNER Name Mtn. Home Highway District Address Mtn. Home

7. WATER LEVEL Static water level 195 feet below land surface. Flowing? No

2. NATURE OF WORK New well Deepened Replacement Abandoned

8. WELL TEST DATA Pump Bailer Air Other

3. PROPOSED USE Domestic Irrigation Test Municipal Industrial Stock Waste Disposal or Injection Other

9. LITHOLOGIC LOG 099205

4. METHOD DRILLED Rotary Air Hydraulic Reverse rotary Cable Dug Other

Table with columns: Hole Diam., Depth (From, To), Material, Water (Yes/No). Contains detailed log entries from 0 to 400 feet depth.

5. WELL CONSTRUCTION Casing schedule: Steel Concrete Other Thickness 2.50 inches Diameter 8 5/8 inches From 1 feet To 61 feet

10. Work started 7/2/79 finished 7/5/79

6. LOCATION OF WELL 61 Sketch map location must agree with written location. County ELMORE NW 1/4 SE 1/4 Sec. 10, T. 3 N/S, R. 6 E/W

11. DRILLERS CERTIFICATION I/We certify that all minimum well construction standards were complied with at the time the rig was removed. Firm Name Middleston Drilling Firm No. 35